




*Figure 1 Tented Camp, as seen from across the stream/ in-channel farm dam to the south-east of the site*



*Figure 2 Office tent and electrical equipment*



*Figure 3 Gravel Road adjacent to office tent and mess tent*



*Figure 4 Steel frame and supporting poles underneath office tent*



*Figure 5 Electrical Supply*



*Figure 6 Electrical Supply with cabling in view*



Figure 7 Buried bio-septic tanks in north-east corner of site



Figure 8 Bio septic tanks, electrical supply, and mess tent- photo indicates proximity to river and in-channel dam



Figure 9 Supporting frame and poles underneath mess tent



Figure 10 Guest support tent and surrounding mulched area



Figure 11 Mulched area around mess tent and landscaping to the south-east



Figure 12 Mess tent



*Figure 13 Landscaping to south of mess tent*



*Figure 14 Landscaping and gabion baskets to south of mess tent*



*Figure 15 Mess tent, as seen from south*



*Figure 16 Compacted, uncovered dirt road to mess tent*



*Figure 17 Uncovered dirt road on site, to the north-west of mess tent*



*Figure 18 Compacted dirt road covered in chips, leading to two central accommodation tents*



*Figure 19 Typical accommodation tent, note raised on steel frame supported by individual poles, composite wood-walling and stretch canvas roof*



*Figure 20 Closer view of platform supporting accommodation tent*



Figure 21 Accommodation tent walls covered in canvas



Figure 22 Accommodation tent and surrounding vegetation



Figure 23 Accommodation tent and power box, steel frame visible



Figure 24 Walkway through centre of accommodation area and sewer line covered in rocks is visible on the right of the photograph



Figure 25 North-eastern most accommodation tent and surrounding vegetation



Figure 26 Section of outer ring road on northern edge of site (1)



Figure 27 Section of outer ring road on northern edge of site (2)




Figure 28 Outer ring road on western edge of site



Figure 29 Accommodation tent off outer ring road




Figure 30 Accommodation tent and surrounding vegetation, located along north-western edge of site



Figure 31 Power box for one of the accommodation tents



Figure 32 Accommodation tent and section of roadway leading to it, covered in chips




*Figure 33 Road leading up to reservoir (1)*



*Figure 34 Inside accommodation tent (2)*



*Figure 35 Reservoir on concrete slab*



*Figure 36 Road leading up to reservoir (2)*



*Figure 37 Section of road on site which is covered in chips*



*Figure 38 Accommodation tent surrounded by olive trees*




*Figure 39 Section of dirt road in southern corner of site*



*Figure 40 Typical state of pastures surrounding the site*



*Figure 41 Second pair of bio septic tanks in north-east corner of site and typical state of surrounding pastures*



*Figure 42 View into accommodation area*

